

New Repair: Light Guide Bundle Replacement

After six months of extensive engineering trials, Olympus is pleased to announce a new, stand-alone Light Guide Bundle Replacement repair for many models of upper and lower GI endoscopes. If the only damage to your endoscope is to the light guide bundle and your scope is one of the approved models listed below, it may qualify for this repair. In the past, if an endoscope had damage to the light guide bundle, the only repair option was to perform a Level 3 refurbishment at a retail price of up to \$7,420. This newest repair represents a considerable savings for our customers.

EVIS-100s	EVIS-130s	EVIS-140s	EVIS-145s	EVIS-160s	Others
GIF-100	GIF-130	GIF-140	GIF-Q145	GIF-160	OSF-V60
GIF-1T100	GIF-1T130-2	GIF-XQ140		GIF-Q160	PCF-S
GIF-2T100		GIF-Q140		GIF-XP160	
		GIF-1T140		GIF-2T160	
		GIF-P140		GIF-Q160Z	
				GIF-XTQ160	
				GIF-1TQ160	
CF-100L-3	CF-130L	CF-140L	CF-Q145L	CF-Q160L	
CF-100I	CF-130I	CF-140I	CF-Q145I	CF-Q160I	
CF-100S	CF-130S	CF-140S		CF-Q160S	
CF-1T100L	PCF-130L	CF-Q140L		CF-Q160AL	
CF-1T100I	PCF-130I	CF-Q140I		CF-Q160AI	
CF-100TL		CF-1T140L		CF-2T160L	
CF-100TI		CF-1T140I		CF-2T160I	
		PCF-140L		CF-Q160ZL	
SIF-100		PCF-140I		CF-Q160ZI	
PCF-100				PCF-160AL	
				PCF-160AI	

